



DATE 2016-11-18	TECHNICIAN Darren Mann	JOB/ORDER # 6714	REFERENCE TEXT Client reference
FIRST NAME Lisa		LAST NAME Lorentzen	
BILLING ADDRESS COMPANY / BILLING NAME 610 - 1060 ALBERNI ST VANCOUVER, V6E4K2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 610 - 1060 ALBERNI ST, BUZ#032 DEIRDRE(TENANT): 604.719.1739 VANCOUVER, V6E4K2 BRITISH COLUMBIA, CANADA	
PHONE 604-418-0323		EMAIL lisalorentzen@gmail.com	

REASON FOR TODAY'S CALL:

The brass piece below the sink connecting the sink to the black abs pipe portion is not screwing on tight, looks corroded?

DESCRIPTION OF WORK PERFORMED:

The threads of the basket strainer corroded and broke off, causing the tailpiece to detach. I replaced the basket strainer & tailpiece and tested by filling and draining the sink multiple times.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Kitchen Sink Basket Strainer	\$159.00	\$159.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$159.00
GST (5%):	\$7.95
TOTAL:	\$166.95

_____ 2016-11-18

 CUSTOMER SIGNATURE DATE