



DATE 2016-11-25	TECHNICIAN Darren Mann	JOB/ORDER # 6739	REFERENCE TEXT Client reference
FIRST NAME Bob		LAST NAME Rennie	
BILLING ADDRESS COMPANY / BILLING NAME 7 - 1650 WEST 1ST AVE VANCOUVER, V6J1G1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 7 - 1650 WEST 1ST AVENUE BUZZER: 307 VANCOUVER, V6J1G1 BRITISH COLUMBIA, CANADA	
PHONE 604.838.5477		EMAIL gail@rennie.com	

REASON FOR TODAY'S CALL:

Toilet flushing mechanism is stuck and has to be manually pulled out in master bedroom. Also, plug in guest bathroom sink needs to be repaired or replaced.

DESCRIPTION OF WORK PERFORMED:

---Ensuite(East Wing): The flush button was sticking, I removed the button, cleaned dust from behind it, and lubricated where it attaches and swivels. Tested and in good working order. Ensuite(West Wing): I re-attached the mechanical lavatory drain stopper and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$109.00
GST (5%):	\$5.45
TOTAL:	\$114.45

_____ 2016-11-25
 CUSTOMER SIGNATURE DATE