



HST #837181627

DATE 2016-12-08	TECHNICIAN Darren Mann		JOB/ORDER # 6787	REFERENCE TEXT Client reference		
FIRST NAME Lawrence		LAST NAME Ng		·		
BILLING ADDRESS HJ WU & COMPANY INC. 303 - 1409 WEST PENDER ST VANCOUVER, V6G 2S3 BRITISH COLUMBIA, CANADA			303 - 1409 WEST PI VANCOUVER, V6G	SERVICE ADDRESS  303 - 1409 WEST PENDER ST, BUZZER 2016 VANCOUVER, V6G 2S3 BRITISH COLUMBIA, CANADA		
PHONE 604-636-1862			EMAIL bctechnology@gmai	EMAIL bctechnology@gmail.com		

REASON FOR TODAY'S CALL: shower drain clogged

## **DESCRIPTION OF WORK PERFORMED:**

I used the PowerSpin drain snake to clear a large amount of hair from the master bathroom shower.

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1	W.	Clean drain using Po	owerSpin / T	Tub/Shower	\$149.00	\$149.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1] Fill in the required details from your		/ARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45	
		INTEREST AT	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  ITEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY		\$156.45	

<u> Thank You!</u>

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.

2016-12-08

DATE

CUSTOMER SIGNATURE