



HST #837181627

DATE 2016-12-15	TECHNICIAN Darren Mann		JOB/O 6804	RDER#	REFERENCE TEXT Client reference
FIRST NAME Myung		LAST NAME Song			
BILLING ADDRESS COMPANY / BILLING NAME 2108 - 7077 BERESFORD BURNABY, V5E4J5 BRITISH COLUMBIA, CANADA	A		14	SERVICE ADDRESS  1104 - 1199 SEYMOUR ST OWNER WILL MEET US THEF BURNABY, BRITISH COLUMBIA, CANADA	
PHONE 778.877.2780				EMAIL sme1546@naver.com	

REASON FOR TODAY'S CALL: garburator jammed

## DESCRIPTION OF WORK PERFORMED:

-I unjammed the garburator by removing a hard chunk of what appeared to be wood or hard food debris. Once unjammed I tested the garburator by filling and

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
Q.ma	(1	eedback Warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00
	our feedbac	k page at:  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF  MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank Youl			TOTAL:	\$114.45
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		

CUSTOMER SIGNATURE

DATE