

HST #837181627

DATE 2016-12-23	TECHNICIAN Darren Mann		JOB/ORDER # 6838	REFERENCE TEXT Client reference	1
FIRST NAME Adam		LAST NAME Martens			
BILLING ADDRESS COMPANY / BILLING NAME 989 BEATTY STREET VANCOUVERV, V6Z3C2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS #1802 - 989 BEATTY STREET VANCOUVERV, V6Z3C2 BRITISH COLUMBIA, CANADA		
PHONE 778 874 7344			EMAIL amartens1@hotmail.com		

REASON FOR TODAY'S CALL:

The tap in the bathtub is leaking, in the unit that I manage.

DESCRIPTION OF WORK PERFORMED:

-I replaced the mixing & pressure balance cartridges within the shower valve and tested.

TECHNICIAN RECOMMENDATIONS:

The handle was missing the set screw so I used a screw from the van to hold it in place.

QTY.	CODE	DESCRIPTION			PRICE
1	//	Replace Mixing & Pressu	re Balance Cartridge - HC180	\$199.00	\$199.00
		warr	<u>PARTS</u> - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$199.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		\$9.95
					\$208.95
		INTE			

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

 $\underline{\textbf{TERMS}}\text{: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK}$ CHARGES. E. & O. E.

2016-12-23

CUSTOMER SIGNATURE