

Phone: 604.727.4484 yaletownplumbing.com

(E) @SimplyPlumbing f YaletownPlumbing

2017-01-10

DATE

HST #837181627

DATE 2017-01-10	TECHNICIAN Darren Mann		JOB/O 6855	RDER #	REFERENCE TEXT Client reference
FIRST NAME Aaron		LAST NAME Alexander	7		
BILLING ADDRESS COMPANY / BILLING NAME 203 - 1140 PENDRELL ST VANCOUVER, V6E1L4 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 203 - 1140 PENDRELL ST, BUZ VANCOUVER, V6E1L4 BRITISH COLUMBIA, CANADA	
PHONE 604.306.9803				EMAIL aaronalexander@gmail.com	

REASON FOR TODAY'S CALL:

My toilet is Installed about 3yrs ago, everything has been fine and then all of sudden in the last 3 months its become loose from the floor. Tried to use some new nuts to tighten it down but still is wobbly.

DESCRIPTION OF WORK PERFORMED:

I lifted the toilet and found that the screws securing the flange in place had popped out. I used Copper strapping and screws to resecure the flange and then reinstalled the toilet with a new wax seal and supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet Wax Seal - Standard	\$189.00	\$189.00
1		\$29.00	\$29.00	
0		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$218.00
Give us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$10.90
			TOTAL:	\$228.90
		VE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTI ED RUSTED DETERPORATION OR LEAD PIESS EXTIRES CLEAN OUTS AND ANY OTHER DAMAGES		

CUSTOMER SIGNATURE