



HST #837181627

DATE 2017-01-10	TECHNICIAN Darren Mann		JOB/ORDER # 6888		REFERENCE TEXT Client reference
FIRST NAME Alexandra		LAST NAME Gill			
BILLING ADDRESS COMPANY / BILLING NAME 1128 IRONWORK PASSAGE VANCOUVER, V6H3R1 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 1128 IRONWORK PASSAGE VANCOUVER, V6H3R1 BRITISH COLUMBIA, CANADA	ı.
PHONE 604.730.2905				EMAIL arockingham@icloud.com	

REASON FOR TODAY'S CALL: toilet running(guest, second floor)

DESCRIPTION OF WORK PERFORMED:

The seat disc(flapper) was warped and the FillValve was sticking, not fully shutting off on occasion. I replaced the FillValve, seat disc, and supply line and tested.

	,				
QTY.	CODE		UNIT PRICE	PRICE	
1	17	Replace FillValve,	\$179.00	\$179.00	
<i>Q.</i>	(I	and hade	ANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$179.00
Gwe us Feedback Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$8.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$187.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

2017-01-10

DATE