



DATE 2017-01-23	TECHNICIAN Darren Mann	JOB/ORDER # 6926	REFERENCE TEXT Client reference
FIRST NAME Ren		LAST NAME Kris	
BILLING ADDRESS COMPANY / BILLING NAME 1501 - 1252 HORNBY ST VANCOUVER, V6Z1W2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1501 - 1252 HORNBY ST, BUZZER 2612 VANCOUVER, V6Z1W2 BRITISH COLUMBIA, CANADA	
PHONE 604.901.8358		EMAIL 2012agl@gmail.com	

REASON FOR TODAY'S CALL:  
leaks under the kitchen sink.

DESCRIPTION OF WORK PERFORMED:  
The leak was coming from the garburator mounting bracket, it had worked itself loose and was allowing water to leak through. I removed the mounting bracket, cleaned it, and reinstalled. Tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2017-01-23

---

CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$109.00
GST (5%):	\$5.45
TOTAL:	\$114.45