



2017-01-27

HST #837181627

DATE 2017-01-27	TECHNICIAN Darren Mann		JOB/ORDER # 6950		REFERENCE TEXT Client reference
FIRST NAME Vera		LAST NAME Sal			
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B 2T4 BRITISH COLUMBIA, CANADA		<u> </u>		SERVICE ADDRESS 1406 - 128 WEST CORDOVA S KEYS AT OFFICE, VACANT UN VANCOUVER, BRITISH COLUMBIA, CANADA	NTIL MONDAY
PHONE 778.980.9100				EMAIL vera@rentitfurnished.com	

REASON FOR TODAY'S CALL:

Replace garburator Check W/D supply hoses

DESCRIPTION OF WORK PERFORMED:

-I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink multiple times while running the garburator. -There was signs of water damage to the flooring around the washing machine but I could not see any sign of leaking from any of the water or drain connections. I suggest having an appliance repairman inspect the machines further.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	/.	Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00
Q.,,,	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$279.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$13.95
			TOTAL:	\$292.95
		WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED RUSTED DETERIORATION OR LEAD PIPES FIXTURES CLEAN OUTS AND ANY OTHER DAMAGES.		