

## 609-77 Walter Hardwick Ave. Vancouver, BC V5Y0C6

Phone: 604.727.4484 yaletownplumbing.com

SimplyPlumbing **F** YaletownPlumbing

HST #837181627

DATE 2017-02-03	TECHNICIAN Darren Mann		JOB/O 6965	RDER #	REFERENCE TEXT Client reference
FIRST NAME Matthew		LAST NAME Cross	7		
BILLING ADDRESS COMPANY / BILLING NAME 1508 - 1783 MANITOBA ST VANCOUVER, V5Y0K1 BRITISH COLUMBIA, CANADA		$\sim$	4	SERVICE ADDRESS 1508 - 1783 MANITOBA STREE BUZZER: 3619 VANCOUVER, V5Y0K1 BRITISH COLUMBIA, CANADA	
PHONE 604.369.6233				EMAIL matty.cross@gmail.com	

## REASON FOR TODAY'S CALL:

Small but persistent leak under my kitchen sink. I haven't been able to find the source, though I suspect it is one of the source pipes rather than the drain or anywhere else (most water seems to be concentrated around where one of the pipes comes up from the floor). There is never a large amount of water, but there are now water stains on the flooring and wall under the sink, and the area is often wet / damp. I need to find and fix the leak.

## DESCRIPTION OF WORK PERFORMED:

I filled and drained the sink while running the garburator and found the p-trap union, and the slipjoint connection to the garburator drain 90 to be loose, allowing water to seep out. I tightened these connections and tested again by filling and draining the sink but the leak persisted. I then noticed that the horizontal drainage is run with more than sufficient grade which is causing the ptrap to angle slightly off vertical. I adjusted the angle of the garburator drain 90 to compensate for this, reconnected the drainage and tested again by filling and draining the sink multiple times while running the garburator. No leaks present.

## **TECHNICIAN RECOMMENDATIONS:**

Even though there are no leaks present I've suggested leaving a small Tupperwear container under the p-trap to help mitigate the chances of water damage in the case that the p-trap developes a leak in the future. If this p-trap does developer a leak in the future, I suggest using a Fernco Coupling to reduce the amount of grade, and re-piping the drainage.

QTY.	CODE	DESCRIPTION	UN		PRICE
1		Labour		\$109.00	\$109.00
0		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S		IBTOTAL:	\$109.00
<b>Give us Feedback</b> Please visit our feedback page at:		LABOUR - 1 YEAR ON NEW UNITS 30 DAY	S ON REPAIR, VOID AFTER 30 DAYS IF	ST (5%):	\$5.45
www.yaletownplumbing.com/feedback [1] Fill in the required details from your		ТО	TAL:	\$114.45	
<u>Thank You!</u>		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN I SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIX RESULTING FROM CLEANING OR REPAIRING EXISTING FIX TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN AF CHARGES. E. & O. E.	TURES, CLEAN OUTS AND ANY OTHER DAMAGES		
		CUSTOMER SIGNATURE	DATE		