

HST #837181627

DATE 2017-02-03	TECHNICIAN Darren Mann		JOB/O 6963	RDER #	REFERENCE TEXT Client reference			
FIRST NAME John		LAST NAME Riordan						
BILLING ADDRESS COMPANY / BILLING NAME 956 RICHARDS ST VANCOUVER, V3T 5E1 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS 956 RICHARDS ST VANCOUVER, V3T 5E1 BRITISH COLUMBIA, CANADA				
PHONE 604.652.9402				EMAIL jriordan@telus.net				

REASON FOR TODAY'S CALL:

The shower handle in the ensuite bathroom has come away from the shower cartridge. I'm not sure if there is a piece missing or if the handle is stripped. If you look at this diagram http://www.moen.ca/replacement-parts/search?context=partorModelNumber&value=82495C it looks like I'm missing the small plastic piece 96988 that fits on the cartridge stem. Give me a call at 604-652-9402 and we can discuss

DESCRIPTION OF WORK PERFORMED:

A piece of the handle adaptor was broken. I replaced this piece and tested.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1		Labour		\$109.00	\$109.00
1		Moen Handle Adaptor Kit		\$15.00	\$15.00
PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$124.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	GST (5%):	\$6.20
		s from your		TOTAL:	\$130.20

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PA MADE THAT SERVICES LISTED ABOVE ARE SATISFA MATERIALS LISTED HEREON ARE CORRECT. YALET SETTLED, RUSTED, DETERIORATION, OR LEAD PIPI RESULTING FROM CLEANING OR REPAIRING EXIST TERMS: NET CASH THE AMOUNTS CONTAINED HER	CTORY COMPLETED AND THA OWN PLUMBING IS NOT RESPO S, FIXTURES, CLEAN OUTS AN ING FIXTURES OR PIPING.	T CHARGES AND DNSIBLE FOR BROKEN, ID ANY OTHER DAMAGES
CHARGES. E. & O. E.		
		2017-02-03
CUSTOMER SIGNATURI		DATE