

HST #837181627

DATE 2017-02-09	TECHNICIAN Darren Mann		JOB/ORDER # 6989		REFERENCE TEXT Client reference	
FIRST NAME Marleena		LAST NAME Markham	9			
BILLING ADDRESS COMPANY / BILLING NAME 2103 - 183 KEEFER PLACE VANCOUVER, V6B2L2 BRITISH COLUMBIA, CANADA			(4)	SERVICE ADDRESS 2103 - 183 KEEFER PLACE, B VANCOUVER, V6B2L2 BRITISH COLUMBIA, CANADA		
PHONE 604.688.2747				EMAIL marleenamarkham@shaw.ca		

REASON FOR TODAY'S CALL:

lavatory sink drain blockage (possibly coconut oil)

DESCRIPTION OF WORK PERFORMED:

-I used the PowerSpin drain snake to clear the guest bathroom lavatory sink drain. I also cleared hair from the master bathroom lavatory drain. -I installed a customer supplied shower head in the guest bathroom.

QTY.	CODE		UNIT PRICE	PRICE	
1		Clean drain using Powe	\$139.00	\$139.00	
Gwe us Feedback WARRANTY:		and hack war	RANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
Please visit our feedback page at:			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$145.95
		IN	TEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY JDE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

Thank You!

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2017-02-09

CUSTOMER SIGNATURE

ralle

DATE