

HST #837181627

DATE 2017-02-15	TECHNICIAN Darren Mann		JOB/ORDER # 6998	REFERENCE TEXT Client reference	
FIRST NAME Georgina		LAST NAME Masana			
BILLING ADDRESS COMPANY / BILLING NAME 1104 - 1455 HOWE ST VANCOUVER, V6Z1C2 BRITISH COLUMBIA, CANADA		1104 - 1455 HOW VANCOUVER, VE	SERVICE ADDRESS 1104 - 1455 HOWE ST, BUZZER 5048 VANCOUVER, V6Z1C2 BRITISH COLUMBIA, CANADA		
PHONE 604.874.3330		EMAIL geo.tapia@aol.co	EMAIL geo.tapia@aol.com		

REASON FOR TODAY'S CALL: Garburator cracked and leaking

DESCRIPTION OF WORK PERFORMED:

I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$309.00 \$309.
<u>Q</u>	, 115 G	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL: \$309.
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		ck page at: Labour - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOL	` '
		ls from your	TOTAL: \$324.
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR	AND R BROKEN, ER DAMAGES

CUSTOMER SIGNATURE

2017-02-15

DATE