

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-03-01	TECHNICIAN Darren Mann		JOB/ORDER # 7051		REFERENCE TEXT Client reference
FIRST NAME Mary Ann		LAST NAME Mulhern	7		
BILLING ADDRESS COMPANY / BILLING NAME 402 - 120 MILROSS AVE VANCOUVER, V6A 4K7 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 402 - 120 MILROSS AVENUE BUZZER: 027 VANCOUVER, V6A 4K7 BRITISH COLUMBIA, CANADA	
PHONE 604.417.3324				EMAIL mamulhern@yahoo.ca	

REASON FOR TODAY'S CALL: Garburator leaking under kitchen sink.

DESCRIPTION OF WORK PERFORMED:

The garburator was leaking right through the bottom and there were cracks in the housing. I replaced the garburator with new and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Supply & Install 1/2	Install 1/2HP Badger5 Garburator				\$319.00
Rung of Goodle al			WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	NYS ON REPAIR, VOID AFTER 30 DAYS IF NITS, OR PAYMENT NOT MADE, ABSOLUTELY NO IATERIALS.	SUBTOTAL:	\$319.00
Give us Geedback page at: <u>www.yaletownplumbing.com/feedback [1]</u> Fill in the required details from your invoice and tell us how we did. <u>Thank You!</u>			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT	GST (5%):		\$15.95	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:		\$334.95	
		SETTLED, RI RESULTING	LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RES USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATH E. & O. E. CUSTOMER SIGNATURE				