

HST #837181627

DATE 2017-03-03	TECHNICIAN Darren Mann		JOB/ORDER # 7022		REFERENCE TEXT Client reference
FIRST NAME Antonio		LAST NAME Hernandez			
BILLING ADDRESS COMPANY / BILLING NAME 306 - 33 WEST PENDER ST VANCOUVER, V6B 0E5 BRITISH COLUMBIA, CANADA			4	#306 - 33 WEST PENDER STR 0417 VANCOUVER, V6B 0E5 BRITISH COLUMBIA, CANADA	
PHONE 604-836-0113				EMAIL antonioghernandez@gmail.com	

## REASON FOR TODAY'S CALL:

Our garbage disposal has started leaking from the bottom. also the the faucet in the kitchen and bathroom needs to be tightened.

## DESCRIPTION OF WORK PERFORMED:

-I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator. -I tightened the nuts that secure the kitchen and lavatory faucets to the countertops.

QTY.	CODE		UNIT PRICE	PRICE	
1		Supply & Install 1/2h	\$319.00	\$319.00	
<i>Q</i>		and a de	VARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$319.00
Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$334.95
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES F & O. F.		

CUSTOMER SIGNATURE

DATE