



DATE 2017-03-03	TECHNICIAN Darren Mann	JOB/ORDER # 7061	REFERENCE TEXT Client reference
FIRST NAME Aidin		LAST NAME Niavarani	
BILLING ADDRESS COMPANY / BILLING NAME 3707 - 928 BEATTY ST VANCOUVER, V6B 0C3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 3707 - 928 BEATTY ST BUZZER: 1294 VANCOUVER, V6B 0C3 BRITISH COLUMBIA, CANADA	
PHONE 604.729.2877		EMAIL aidinnz@hotmail.com	

REASON FOR TODAY'S CALL:

The flush tank in the toilet is having problems filling up with water. It also seems to be leaking water (from time to time we hear the toilet tank filling up). I think the units inside of the tank are defective and may need to be repaired or replaced.

DESCRIPTION OF WORK PERFORMED:

I replaced the toilet fillvalve, flapper, and supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet FillValve, Flapper, Supply - Standard	\$169.00	\$169.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2017-03-03

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$169.00
GST (5%):	\$8.45
TOTAL:	\$177.45