

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-03-10	TECHNICIAN Darren Mann		JOB/ORDER # 7087		REFERENCE TEXT Client reference
FIRST NAME Stefan		LAST NAME Behan	7		
BILLING ADDRESS COMPANY / BILLING NAME 407 INGLEWOOD PLACE WEST VANCOUVER, V7T1X2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 1201 - 1067 MARINASIDE CRE JAEWON: 604.396.2019 BUZ#1068 WEST VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.925.3330				EMAIL stumbo35@gmail.com	

REASON FOR TODAY'S CALL:

tub draining slow. tenant tried to clear it with snake. the snake is now stuck and he cannot remove it.

DESCRIPTION OF WORK PERFORMED:

The tenant tried to clear the blocked tub drain using a toilet auger which ended up twisting around the lift rod spring within the overflow. I was able to remove the toilet auger and used our PowerSpin drain snake to clear large clumps of hair from further down the drain. Tested by filling the tub half way and draining.

QTY .	CODE		UNIT PRICE	PRICE	
1	1.	Clean drain using	\$149.00	\$149.00	
Give us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your		and a al	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$156.45
	i tell us how v		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. 2017-03-10 CUSTOMER SIGNATURE DATE		
			CUSTOMER SIGNATURE DATE		