



DATE 2017-03-23	TECHNICIAN Darren Mann	JOB/ORDER # 7113	REFERENCE TEXT Client reference
FIRST NAME BJ		LAST NAME Kim	
BILLING ADDRESS BNA INVESTMENTS LTD 506 - 1500 HORNBY ST VANCOUVER, V6Z2R1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 3008 - 668 CITADEL PARADE LUKE AT 604-341-3158 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.351.6860		EMAIL bjkim@hotmail.com	

REASON FOR TODAY'S CALL:
garburator and drain issues *key and fob with concierge

DESCRIPTION OF WORK PERFORMED:
I was able to free up the jammed garburator and get it working again but during testing noticed there was a crack in the housing allowing water to leak out. I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$279.00
GST (5%):	\$13.95
TOTAL:	\$292.95

_____ 2017-03-23
 CUSTOMER SIGNATURE DATE