

2017-03-27 DATE

HST #837181627

| DATE 2017-03-27 | TECHNICIAN Darren Mann | | JOB/ORDER # 7137 | REFERENCE TEXT Client reference |
|--|---------------------------|------------------------|---|---------------------------------|
| FIRST NAME Miyuki | | LAST NAME Yamashita | | |
| BILLING ADDRESS COMPANY / BILLING 1267 MELVILLE ST. VANCOUVER, V6E0A BRITISH COLUMBIA, | 4 5 | | SERVICE ADDRESS 1267 MELVILLE ST. VANCOUVER, V6E0A BRITISH COLUMBIA, | |
| PHONE 778.885.0526 | | | EMAIL miyuki0805@gmail.cor | n |

REASON FOR TODAY'S CALL:

I have a bathtub/shower combination, and it's supposed to push the knob to start the shower, but the knob part doesn't come out properly, so I've closed the knob completely and been using only as a shower otherwise the water leaks and pushes the knob out.

DESCRIPTION OF WORK PERFORMED:

| QTY. CODE | DESCRIPTION | UNIT PRICE | PRICE |
|---|---|------------|----------|
| 1 Quoted | Price | \$119.00 | \$119.00 |
| Gwe us Feedl | WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY | SUBTOTAL: | \$119.00 |
| Please visit our feedback page at: | LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF | GST (5%): | \$5.98 |
| www.yaletownplumbing.com/feed | | TOTAL: | \$124.95 |
| invoice and tell us how we did. Thank You! | INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. | | |

CUSTOMER SIGNATURE