





HST #837181627

DATE 2017-03-29	TECHNICIAN Darren Mann		JOB/ORDER # 7156		REFERENCE TEXT Client reference				
FIRST NAME Tara		LAST NAME Mews	97						
BILLING ADDRESS COMPANY / BILLING NAME 205 E 10TH AVENUE VANCOUVER, V5T 4V6 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 203 - 205 E 10TH AVENUE BUZZER: CALL CELL VANCOUVER, V5T 4V6 BRITISH COLUMBIA, CANADA					
PHONE 6047238148				EMAIL tlmews@gmail.com					

REASON FOR TODAY'S CALL:

leak under the kitchen sink when d/w runs *give heads up

DESCRIPTION OF WORK PERFORMED:

The garburator was leaking through cracks in the housing. I removed the garburator, installed a basket strainer in its place, and repiped the ABS drainage.

QTY.	CODE		UNIT PRICE	PRICE	
1		Delete Garburator & Re-Pipe	\$219.00	\$219.00	
1	1/2	MewMew Discount		-\$20.00	-\$20.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		warranty:	: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$199.00
				GST (5%):	\$9.95
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HERERY		\$208.95

<u> Thank You!</u>

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

 $\underline{\textbf{TERMS}}\text{: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK}$

CHARGES, E. & O. E.

2017-03-29

CUSTOMER SIGNATURE