



DATE 2017-04-05	TECHNICIAN Darren Mann	JOB/ORDER # 7173	REFERENCE TEXT Client reference
FIRST NAME Michael		LAST NAME Makowy	
BILLING ADDRESS COMPANY / BILLING NAME 301 - 531 BEATTY ST VANCOUVER, V6B 0C5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2406 - 501 PACIFIC ST, BUZ#7636 MANDY604-825-7636 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.771.3625		EMAIL mmakowy@yahoo.com	

REASON FOR TODAY'S CALL:
kitchen sink draining slowly. *buz not working

DESCRIPTION OF WORK PERFORMED:
The garburator was jammed and the buildup of rust inside was clogging up the drain. I was able to free up the garburator and tested by filling and draining the sink multiple times.

TECHNICIAN RECOMMENDATIONS:
The garburator grinding chamber has deteriorated quite badly and will have to be replaced or removed ASAP.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$109.00
GST (5%):	\$5.45
TOTAL:	\$114.45

_____ 2017-04-05
 CUSTOMER SIGNATURE DATE