

HST #837181627

DATE 2017-03-22	TECHNICIAN Darren Mann		JOB/ORDER # 7082	REFERENCE TEXT Client reference	
FIRST NAME Gillian		LAST NAME Baxter			
BILLING ADDRESS COMPANY / BILLING 2071 CREELMAN AVI VANCOUVER, V6J 10 BRITISH COLUMBIA,	E C2	79	SERVICE ADDRESS 2071 CREELMAN AV VANCOUVER, V6J 1 BRITISH COLUMBIA	/E C2	
PHONE 1.970.379.9390			EMAIL gillianbaxter@comca	st.net	

REASON FOR TODAY'S CALL:

2 tub/showers not getting very hot water.

DESCRIPTION OF WORK PERFORMED:

---Mar22: I made a visit to the house and found that the Thermostatic cartridges in both Riobel shower valves will have to be replaced. I will contact Riobel and order the parts. ---Apr6: Riobel sent me 2 Thermostatic cartridges under warranty. I installed both cartridges and tested.

QIT.	CODE	DESCRIPTION	UNII PRICE	PRICE
1		Labour(Mar22)	\$109.00	\$109.00
1	1/2	Replace Thermostatic Cartridge - Riobel	\$139.00	\$139.00
1		Replace Thermostatic Cartridge - Riobel(each additional)	\$79.00	\$79.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$327.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$16.35
			TOTAL:	\$343.35

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

CUSTOMER SIGNATURE