

Phone: 604.727.4484 yaletownplumbing.com

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE 2017-04-11	TECHNICIAN Darren Mann		JOB/O 7198	RDER #	REFERENCE TEXT Client reference
FIRST NAME Rita		LAST NAME Lau	7		
BILLING ADDRESS COMPANY / BILLING NAME 844 WEST 6TH AVE VANCOUVER, V5Z 1A6 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 844 WEST 6TH AVE BUZZER: 1162 VANCOUVER, V5Z 1A6 BRITISH COLUMBIA, CANADA	
PHONE 604.782.0987				EMAIL ritamak7@gmail.com	

REASON FOR TODAY'S CALL:

-Broken garburator. Requires replacement. -Tub faucet won't fully shut off(master bathroom).

CHARGES. E. & O. E.

## DESCRIPTION OF WORK PERFORMED:

-I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator. -I replaced the faulty cartridge in the master bathroom tub filler(K35B) and tested.

QTY.	CODE	DESCRIPTION				PRICE
1		Supply & Install 1/2HP Badger5 Garburator			\$319.00	\$319.00
1		Replace K35B Cartridge	\$89.00	\$89.00		
Give us Feedback warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$408.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$20.40	
		s from vour	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		TOTAL:	\$428.40

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

invoice and tell us how we did.

Thank You!

M	2017-04-11
GUSTOMER SIGNATURE	DATE