

(SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-04-12	TECHNICIAN Darren Mann		JOB/ORDER # 7193		REFERENCE TEXT Client reference
FIRST NAME Eric Enno		LAST NAME Tamm	7		
BILLING ADDRESS COMPANY / BILLING NAME 2002 - 125 MILROSS AVE VANCOUVER, V6A 0A1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 2002 - 125 MILROSS AVE BUZZER: 2002 VANCOUVER, V6A 0A1 BRITISH COLUMBIA, CANADA	
PHONE 604.562.5310				EMAIL ericennotamm@gmail.com	

REASON FOR TODAY'S CALL:

When the dishwasher is on or when we put any water down the sink, the garbage disposal begins to leak.

DESCRIPTION OF WORK PERFORMED:

-I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE			UNIT PRICE	PRICE		
1		Supply & Install 1/2HP Badger5 Garburator				\$319.00	\$319.00
0		and a du	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$319.00
Give us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 3 MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE		GST (5%):	\$15.95	
		INTEREST AT	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$334.95		
	I tell us how v		MATERIALS LIS SETTLED, RUS RESULTING FF	ERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND TH STED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RES STED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS ROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. ASSH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATH & O. E. CUSTOMER SIGNATURE	SPONSIBLE FOR BROKEN, AND ANY OTHER DAMAGES		