



DATE 2017-04-13	TECHNICIAN Darren Mann	JOB/ORDER # 7200	REFERENCE TEXT Client reference
FIRST NAME Jeff		LAST NAME Baldemoro	
BILLING ADDRESS COMPANY / BILLING NAME 3107 - 928 BEATTY ST VANCOUVER, V6Z 3G6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 3107 - 928 BEATTY ST BUZZER: 1253 VANCOUVER, V6Z 3G6 BRITISH COLUMBIA, CANADA	
PHONE 778.386.8144		EMAIL mjef_d@yahoo.com	

REASON FOR TODAY'S CALL:
 Toilet tank water fill valve repair/replacement. Toilet tank's water fill valve is leaking water even after the tank is fill up to the water line causing the tank to overflow and water runs into the bowl.


DESCRIPTION OF WORK PERFORMED:
 I replaced the FillValve, flapper, and supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Toilet FillValve, Flapper, Supply - Standard	\$169.00	\$169.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



 CUSTOMER SIGNATURE

2017-04-13

 DATE

SUBTOTAL:	\$169.00
GST (5%):	\$8.45
TOTAL:	\$177.45