

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2017-04-24	1201111111111		JOB/O 7232	RDER #	REFERENCE TEXT Client reference			
FIRST NAME Easyrent		LAST NAME Admin	97					
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  1201 - 1188 HOWE ST, BUZ#0177 DEREK: 604-505-6315 VANCOUVER, BRITISH COLUMBIA, CANADA					
PHONE 604.662.3279				EMAIL info@easyrent.ca				

REASON FOR TODAY'S CALL: toilet shut off valve leaking.

## DESCRIPTION OF WORK PERFORMED:

The leak was coming from the stem of the shut off valve located behind the toilet. I tightened the packing nut which resolved this leak but during testing noticed that the supply line was also leaking. I replaced the supply line and tested again. Toilet flushing normally with no sign of leaking.

G(11.	CODE		DESCRIPTION	OMIT I MOL	TRIOL
1		Discount Labour		\$99.00	\$99.00
1	2121352	B1-16DL 3/8X20 SPEEDI+	SPEEDI+ WC CONN		\$11.00
<b>2</b>	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.50
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$115.50

<u> Thank You!</u>

invoice and tell us how we did.

MADE THAT SERVICES LISTE MATERIALS LISTED HEREON SETTLED, RUSTED, DETERIO	TE IS CHARGED ON PAST DUE AG D ABOVE ARE SATISFACTORY C ARE CORRECT. YALETOWN PLU RATION, OR LEAD PIPES, FIXTUR OR REPAIRING EXISTING FIXTUR	OMPLETED AND THAT CHAR MBING IS NOT RESPONSIBLI RES, CLEAN OUTS AND ANY	GES AND E FOR BROKEN,
	UNTS CONTAINED HEREIN ARE F		ID TRUCK
CHARGES. E. & O. E.			
		2	017-04-24
(	CUSTOMER SIGNATURE		DATE