



**8947**

HST #837181627

DATE 2017-05-04	TECHNICIAN Darren Mann	JOB/ORDER # 7257	REFERENCE TEXT Client reference
FIRST NAME Darlene		LAST NAME Johnson	
BILLING ADDRESS COMPANY / BILLING NAME 202 - 1000 BEACH AVE VANCOUVER, V6E4M2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 202 - 1000 BEACH AVE BUZZER: 202 VANCOUVER, V6E4M2 BRITISH COLUMBIA, CANADA	
PHONE 604-408-8937		EMAIL Darlene@mdhk.ca	

REASON FOR TODAY'S CALL:  
 Our Kohler shower head has developed a persistent leak.

DESCRIPTION OF WORK PERFORMED:  
 I replaced the mixing and pressure balance cartridges within the shower valve and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Mixing & Pressure Balance Cartridges - Kohler	\$259.00	\$259.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$259.00
GST (5%):	\$12.95
TOTAL:	\$271.95

  
 \_\_\_\_\_  
 CUSTOMER SIGNATURE

2017-05-04  
 \_\_\_\_\_  
 DATE