



2017-05-16

DATE

HST #837181627

DATE 2017-05-16	TECHNICIAN Darren Mann		JOB/ORDER # 7304		REFERENCE TEXT Client reference
FIRST NAME Shenaz		LAST NAME Madhani			
BILLING ADDRESS		///	SERVIC	E ADDRESS	
2113 - 610 GRANVILLE ST VANCOUVER, V6C 3T3 BRITISH COLUMBIA, CANADA			VANCO	10 GRANVILLE ST UVER, I COLUMBIA, CANADA	
PHONE 1.438.491.8091			EMAIL nicolas.	morant@corporatestays	.com

## REASON FOR TODAY'S CALL:

Leaking garburator.

## **DESCRIPTION OF WORK PERFORMED:**

The garburator was leaking through the mounting bracket as well as out of the bottom of the unit. I replaced the garburator with a new Badger5 and tested by filling

QTY.	CODE		DESCRIPTION			
1	//	Supply & Install 1/2HP Badger5 Garburator			\$319.00	
Gwe us Feedback warrai			ARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$319.00	
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank You!		ck page at:	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	GST (5%):	\$15.9	
		ils from your		TOTAL:	\$334.9	
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.			

CUSTOMER SIGNATURE