

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-05-11	TECHNICIAN Darren Mann		JOB/O 7282	RDER #	REFERENCE TEXT Client reference
FIRST NAME JOSHUA		LAST NAME KESSELMAN	7		
BILLING ADDRESS COMPANY / BILLING NAME 4715 DRUMMOND DRIVE VANCOUVER, V6T1B3 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 4715 DRUMMOND DRIVE VANCOUVER, V6T1B3 BRITISH COLUMBIA, CANADA	
PHONE 6047305813				EMAIL jdk@jdkone.com	

REASON FOR TODAY'S CALL:

install new faucet part inspect dripping shower

**DESCRIPTION OF WORK PERFORMED:** 

---Master Ensuite: -The leak was coming from the threads of the shower arm. I removed the shower head and applied Teflon tape before reinstalling. Tested and no leaks present. -I replaced the aerator in the lavatory faucet. ---Powder Room: I installed the part Josh received from Jado and tested.

<b>QTY</b> .	CODE	DESCRIPTION				UNIT PRICE	PRICE
1.5		Labour	7			\$109.00	\$163.50
0		and had	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$163.50
Give us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY N WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		GST (5%):	\$8.18	
				DGEMENT IS HEREBY	TOTAL:	\$171.68	
		SETTLED, RU RESULTING F	ISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPON ISTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND "ROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIA & O. E.				
				CUSTOMER SIGNATURE	DATE		