



DATE 2017-05-18	TECHNICIAN Darren Mann	JOB/ORDER # 7295	REFERENCE TEXT Client reference
FIRST NAME Jan		LAST NAME Brzeski	
BILLING ADDRESS COMPANY / BILLING NAME 2501 - 928 BEATTY ST VANCOUVER, V6Z 3G6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2501 - 928 BEATTY STREET BUZZER: 1188 VANCOUVER, V6Z 3G6 BRITISH COLUMBIA, CANADA	
PHONE 604-721-0154		EMAIL wjbrzeski.ipti@novuscom.net	

REASON FOR TODAY'S CALL:
Hot water only dripping in our kitchen tap, while cold water is OK.

DESCRIPTION OF WORK PERFORMED:
The hot shut off valve (connected to the kitchen faucet) was breaking down, causing bits of debris to clog up the hot supply line. I flushed the debris out of the hot line and repaired the hot shut off valve by replacing the washer, stem, packing, packing nut, and handle. Tested and pressure is back to normal.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Repair 1/2" x 3/8" Angle or Straight Stop	\$139.00	\$139.00


Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:		\$139.00
GST (5%):		\$6.95
TOTAL:		\$145.95

 <hr/> CUSTOMER SIGNATURE	2017-05-18 <hr/> DATE
---	--------------------------