



HST #837181627

DATE 2017-06-09	TECHNICIAN Darren Mann		JOB/ORDER # 7362	REFERENCE TEXT Client reference	
FIRST NAME Alex		LAST NAME Montoya			
BILLING ADDRESS COMPANY / BILLING NAME #1105 - 789 DRAKE ST VANCOUVER, BRITISH COLUMBIA, CANADA		#1105 - 789 DRA MACKENZIE: 60 VANCOUVER,	#1105 - 789 DRAKE ST, BUZ#177 MACKENZIE: 604.812.1894 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.733.2527			EMAIL alex@nacbr.com		

REASON FOR TODAY'S CALL:

kitchen sink drain backing up. Garburator not working

DESCRIPTION OF WORK PERFORMED:

The garburator was jammed, causing the sink to drain very slowly. I was able to free up the garburator but during testing noticed it was leaking through the bottom. I replaced the garburator with new and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE		UNIT PRICE	PRICE	
1		Supply & Install 1/2HP	upply & Install 1/2HP Badger5 Garburator		
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		WAR	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		\$319.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.95
		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		\$334.95
		we did.	NADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND INTERPRETATION OF THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND INTERPRETATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES ESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. ERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK HARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE