



HST #837181627

DATE 2017-06-12	TECHNICIAN Darren Mann		JOB/ORDER # 7382	REFERENCE TEXT Client reference		
		LAST NAME Blakeney				
BILLING ADDRESS COMPANY / BILLING NAME 3003 - 1199 MARINASIDE CRES VANCOUVER, V6Z 2Y2 BRITISH COLUMBIA, CANADA		907 - 1225 RICHARE VANCOUVER, V6B	SERVICE ADDRESS 907 - 1225 RICHARDS ST VANCOUVER, V6B 1E6 BRITISH COLUMBIA, CANADA			
PHONE 604-266-5379			EMAIL rebecca.blakeney@y	EMAIL rebecca.blakeney@yahoo.ca		

REASON FOR TODAY'S CALL:

Thank You!

Tenant reports that the toilet tank is refilling very slowly, and is audibly hissing. He estimates the toilet can flush only once per hour at the rate the tank is filling.

DESCRIPTION OF WORK PERFORMED:

The FillValve was malfunctioningand the flapper was starting to warp. I replaced the FillValve, flapper, and supply line. Tested and in good working order.

QTY.	CODE	DESCRIPTION			PRICE
1		Replace Toilet FillValve, Flapper, Supply - Standard			\$169.00
invoice and tell us how we did.		war	RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00
			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$8.45
		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. ITEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$177.45
		we did.	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN.		

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

CUSTOMER SIGNATURE

ABlako

CHARGES, E. & O. E.

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES

2017-06-12

DATE

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK