



HST #837181627

DATE 2017-06-19	TECHNICIAN Darren Mann		JOB/ORDER # 7345		REFERENCE TEXT Client reference	
FIRST NAME Adrien		LAST NAME Amadeo-Vitton	е			
BILLING ADDRESS COMPANY / BILLING NAME 3105 - 1408 STRATHMORE MEWS VANCOUVER, V6Z 3A9 BRITISH COLUMBIA, CANADA		4	4	SERVICE ADDRESS  3105 - 1408 STRATHMORE MEWS, BUZZER 1206 VANCOUVER, V6Z 3A9 BRITISH COLUMBIA, CANADA		
PHONE 604.202.8251				EMAIL horsepowernow@gmail.com		

REASON FOR TODAY'S CALL: Leaking garburator

## **DESCRIPTION OF WORK PERFORMED:**

-The garburator was leaking through the bottom and could not be repaired. I replaced the garburator with new and tested. -While onsite it was mentioned that the kitchen faucet was wobbly and there is also a leak coming from the right side of the kitchen sink. The base of the kitchen faucet was installed incorrectly. I installed this base properly and tested. The basket strainer in the right side of the sink is broken internally and will have to be replaced.

QTY.	CODE	DESCRIPTION			PRICE
1		Supply & Install 1/2HP Badger5	\$319.00	\$319.00	
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your  WARRANTY:  PARTS - SUBJECT TO MANUFACTURER'S WARRANTY  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		SUBTOTAL:	\$319.00		
				GST (5%):	\$15.95
		s from your			\$334.95

<u> Thank You!</u>

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

CUSTOMER SIGNATURE DATE