



DATE 2017-06-21	TECHNICIAN Darren Mann	JOB/ORDER # 7421	REFERENCE TEXT Client reference
FIRST NAME Adrien		LAST NAME Amadeo-Vittone	
BILLING ADDRESS COMPANY / BILLING NAME 3105 - 1408 STRATHMORE MEWS VANCOUVER, V6Z 3A9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 3105 - 1408 STRATHMORE MEWS, BUZZER 1206 VANCOUVER, V6Z 3A9 BRITISH COLUMBIA, CANADA	
PHONE 604.202.8251		EMAIL horsepowernow@gmail.com	

REASON FOR TODAY'S CALL:
 Replace kitchen sink strainer assembly

DESCRIPTION OF WORK PERFORMED:
 The right side basket strainer was broken internally, causing it to leak. I replaced the basket strainer with new and tested by filling and draining the sink multiple times.


QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Basket Strainer	\$149.00	\$149.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

 <hr/> CUSTOMER SIGNATURE	2017-06-21 <hr/> DATE
--	--------------------------

SUBTOTAL:	\$149.00
GST (5%):	\$7.45
TOTAL:	\$156.45