

(SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-06-28	TECHNICIAN Darren Mann		JOB/ORDER # 7443		REFERENCE TEXT Client reference	
FIRST NAME Elana		LAST NAME Brief	7			
BILLING ADDRESS COMPANY / BILLING NAME 302 - 1750 WEST 2ND AVE. VANCOUVER, V6J 1H6 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 302 - 1750 WEST 2ND AVE., BUZZER 53 VANCOUVER, V6J 1H6 BRITISH COLUMBIA, CANADA		
PHONE 6047809373				EMAIL elanabrief@gmail.com		

REASON FOR TODAY'S CALL:

Our toilet tank is running constantly. After the tank is filled, water continues to flow into overflow tube.

DESCRIPTION OF WORK PERFORMED:

-I replaced the toilet fillvalve, flapper, and supply line. Tested and in good working order.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Replace Toilet FillV	olace Toilet FillValve, Flapper, Supply - Standard				
Concert Tool and		PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	SUBTOTAL:	\$169.00			
Give us Geedback page at: <u>www.yaletownplumbing.com/feedback [1]</u> Fill in the required details from your invoice and tell us how we did. <u>Thank You!</u>			GST (5%):	\$8.45			
			TOTAL:	\$177.45			
		MATERIALS I SETTLED, RU RESULTING	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, JSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK . & O. E. COSTOMER SIGNATURE CUSTOMER SIGNATURE DATE				