

HST #837181627

DATE 2017-06-06	TECHNICIAN Darren Mann		JOB/ORDER # 7358	:	REFERENCE TEXT Client reference	
FIRST NAME Don		LAST NAME Wright				
BILLING ADDRESS COMPANY / BILLING NAME 1282 WEST 6TH AVE VANCOUVER, V6H1A5 BRITISH COLUMBIA, CANADA		19	1282 V VANC	CE ADDRESS VEST 6TH AVE OUVER, V6H1A5 SH COLUMBIA, CANADA		
PHONE 604.230.1907			EMAIL dw927	7@gmail.com		

REASON FOR TODAY'S CALL:

Our bathroom sink drain is clogged and another one should be checked as well.

DESCRIPTION OF WORK PERFORMED:

---June6: I ran the PowerSpin drain snake through the lavatory sinks on the 1st and 2nd floors. Tested by filling and draining the sinks multiple times. -The 1st floor toilet runs periodically. I found the flushvalve gasket to be warping with bubbles. I have taken measurements of the gasket and will inquire with our wholesalers as to where parts for Neptune toilets can be found. ---June 28: I returned with a new flushvalve gasket and installed. Tested and in good working order.

QTY.	CODE	DESCRIPTION			PRICE
1		Clean drain using PowerSpin / Lavatory			\$139.00
1		Replace Flush Valve Gasket		\$119.00	\$119.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		SUBTOTAL:	\$258.00		
			MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$12.90
				TOTAL:	\$270.90

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2017-06-06

DATE

CUSTOMER SIGNATURE