



HST #837181627

DATE 2017-06-29	TECHNICIAN Darren Mann		JOB/ORDER # 7448	REFERENCE TEXT Client reference	
FIRST NAME Sonia		LAST NAME Gin			
BILLING ADDRESS COMPANY / BILLING NAME 806 - 125 MILROSS AVE VANCOUVER, V6A0A1 BRITISH COLUMBIA, CANADA			806 - 125 MILROSS A VANCOUVER, V6A0	SERVICE ADDRESS  806 - 125 MILROSS AVE, BUZZER 0806 VANCOUVER, V6A0A1 BRITISH COLUMBIA, CANADA	
PHONE 604.732.1790			EMAIL raygin123@gmail.cor	n	

## REASON FOR TODAY'S CALL:

Shower making loud vibrate hammering noises from the hot side of the tap. model name of tap (MOEN) I'm the first own and this building is now on it's 10yrs...

## **DESCRIPTION OF WORK PERFORMED:**

There was water hammer happening when the shower was activated. I tried replacing the tub spout diverter but the issue persisted, I then replaced the cartridge within the shower valve and the issue still persisted. I finally removed the shower head and removed some debris from within. Reattached the head and tested. The water hammering has stopped:)

QTY.	CODE	DESCRIPTION			PRICE
1	/	Labour		\$109.00	\$109.00
		warrai	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF  MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	SUBTOTAL:	\$109.00
				GST (5%):	\$5.45
				TOTAL:	\$114.45
		INTER	EST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		

Thank You!

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. DATE

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,