

Phone: 604.727.4484 yaletownplumbing.com

2017-07-04

DATE

HST #837181627

DATE 2017-07-04	TECHNICIAN Darren Mann		JOB/ORDER # 7462	REFERENCE TEXT Client reference
FIRST NAME Grant		LAST NAME Russell		
BILLING ADDRESS COMPANY / BILLING NAME 3007 - 193 AQUARIUS MEWS VANCOUVER, V6Z 2Z2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 3007 - 193 AQUARIUS MEWS BUZZER: 1205 VANCOUVER, V6Z 2Z2 BRITISH COLUMBIA, CANADA		
PHONE 604.364.3258		EMAIL grantrussell@kpmg.ca	EMAIL grantrussell@kpmg.ca	

REASON FOR TODAY'S CALL:

Faucet leaking; sink stopper won't release water Garburetor is not working

DESCRIPTION OF WORK PERFORMED:

---Guest Bathroom: The lavatory faucet is leaking through the cartridge. This cartridge will have to be replaced but I cannot find a name brand anywhere on the faucet and I do not recognize the cartridge. The pop-up sink stopper was stuck in the closed position. I was able to remove the stopper but the pop-up mechanism is broken internally and I could not repair it. This will have to be replaced. ---Garburator: I was able to unjam the garburator and tested by filling and draining the sink multiple times while running the garburator. Nothing was pulled out of the garburator, whatever caused it to seize up was likely pushed through and washed down the

QTY.	CODE	DESCRIPTION		PRICE
1		Labour	\$109.00	\$109.00
Q.,,,		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL	\$109.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VO		\$5.45
			TOTAL:	\$114.45
		we did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED A MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NO SETTLE PROPERTY DESCRIPTION FOR HEAD PURPLE SATISFACE.	ND THAT CHARGES AND FRESPONSIBLE FOR BROKEN, UTS AND ANY OTHER DAMAGES IG.	

CUSTOMER SIGNATURE