

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-07-05	TECHNICIAN Darren Mann		JOB/ORDER # 7456		REFERENCE TEXT Client reference
FIRST NAME Olga		LAST NAME Krelin	7		
BILLING ADDRESS		10	1.	SERVICE ADDRESS	
2893 WEMBLEY PL NORTH VANCOUVER, V7J3C1 BRITISH COLUMBIA, CANADA			1002 - 183 KEEFER PL RUSS: 778.899.3781 NORTH VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.317.8665				EMAIL olga@olgakrelin.com	

REASON FOR TODAY'S CALL: garburator broken.

DESCRIPTION OF WORK PERFORMED:

The garburator grinding chamber had deteriorated to the point that chunks were flaking off. I replaced the garburator with new abd tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Supply & Install 1/2	Supply & Install 1/2HP Badger5 Garburator				\$319.00
Rung of Gradl and			WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARR.	SUBTOTAL:	\$319.00	
Give us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON F MAINTENANCE IS NOT DONE ON NEW UNITS, OF	GST (5%):	\$15.95		
			WARRANTY ON CUSTOMER SUPPLIED MATERIA	TOTAL:	\$334.95		
		MATERIALS SETTLED, R RESULTING	SERVICES LISTED ABOVE ARE SATISFACTORY COM LISTED HEREON ARE CORRECT. YALETOWN PLUME USTED, DETERIORATION, OR LEAD PIPES, FIXTURES FROM CLEANING OR REPAIRING EXISTING FIXTURE T CASH THE AMOUNTS CONTAINED HEREIN ARE FOR E. & O. E.	BING IS NOT RESPONSIBLE FOR BROKEN, S, CLEAN OUTS AND ANY OTHER DAMAGES SS OR PIPING.			
				CUSTOMER SIGNATURE	DATE		