



DATE 2017-07-07	TECHNICIAN Darren Mann	JOB/ORDER # 7453	REFERENCE TEXT Client reference
FIRST NAME Christopher		LAST NAME Neilson	
BILLING ADDRESS COMPANY / BILLING NAME 1210 - 819 HAMILTON ST VANCOUVER, V6B6M2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1210 - 819 HAMILTON ST BUZZER: 227 VANCOUVER, V6B6M2 BRITISH COLUMBIA, CANADA	
PHONE 1.226.792.9737		EMAIL chris_neilson@hotmail.com	

REASON FOR TODAY'S CALL:

No hot water to kitchen sink. There's hot water making it through the shut-off valve, but nothing through the faucet supply line.

DESCRIPTION OF WORK PERFORMED:

The hot shut off valve was breaking down internally, allowing bits of rubber to get caught up within the supply line of the faucet. I repaired this valve by replacing the washer, stem, packing, packing nut, and handle. I then flushed debris out of the hot supply line and tested. Pressure is back to normal.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Repair 1/2" x 3/8" Angle or Straight Stop	\$139.00	\$139.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2017-07-07

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$139.00
GST (5%):	\$6.95
TOTAL:	\$145.95