

HST #837181627

DATE 2017-07-07	TECHNICIAN Darren Mann		JOB/O 7476	RDER #	REFERENCE TEXT Client reference
FIRST NAME Braden		LAST NAME Evans	7		
BILLING ADDRESS COMPANY / BILLING NAME 507 - 583 BEACH CR. VANCOUVER, V6Z3E6 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 507 - 583 BEACH CR. VANCOUVER, V6Z3E6 BRITISH COLUMBIA, CANADA	
PHONE 778.388.3433				EMAIL braden@numericalorder.com	

REASON FOR TODAY'S CALL:

I have water seeping from the base of my toilet, thinking the wax seal must be replaced.

## DESCRIPTION OF WORK PERFORMED:

I found the water to be leaking from between the tank and the bowl, running down the right side of the rear of the bowl, and collecting on the floor. I removed the tank and reinstalled with a new tank to bowl gasket, tank bolts, and supply line. Tested and no other leaks detected.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE	
1	1	Replace Tank To E	Replace Tank To Bowl Gasket - Standard			
0		and a du	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00	
<b>Gwe us Feedback</b> Please visit our feedback page at:			ABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$8.45	
	www.yaletownplumbing.com/feedback [1] Fill in the required details from your		WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$177.45	
	t tell us how v		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FLYTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.			