

(B) @SimplyPlumbing | YaletownPlumbing



HST #837181627

DATE 2017-04-24	TECHNICIAN Darren Mann		JOB/ORDER # 7234		REFERENCE TEXT Client reference	
FIRST NAME Vera		LAST NAME Sal				
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B 2T4 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 607 - 522 WEST 8TH AVE SUITE VACANT: KEYS READY VANCOUVER, BRITISH COLUMBIA, CANADA		
ENT IT FURNISHED 10 - 1020 MAINLAND STREET ANCOUVER, V6B 2T4				EMAIL vera@rentitfurnished.com		

REASON FOR TODAY'S CALL:

laundry shut off valve not working.

DESCRIPTION OF WORK PERFORMED:

I made a trip to the unit and found that there are actually isolating valves just behind the laundry shut off valves and they are working fine. I explained to Vera how they are operated and asked her to pass this info on to the appliance guys.

QTY.	CODE			DESCRIPTION		UNIT PRICE	PRICE
1	/	Discount Labour	٧.,			\$99.00	\$99.00
Gwe us Feedback Please visit our feedback page at:		PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	SUBTOTAL:	\$99.00			
				GST (5%):	\$4.95		
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			TOTAL:	\$103.95			
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HE MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROWN SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DATESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		ONSIBLE FOR BROKEN, ND ANY OTHER DAMAGES			
			<u> </u>		2017-04-24		
				CUSTOMER SIGNATURE	DATE		