



2017-07-11

HST #837181627

DATE 2017-07-11	TECHNICIAN Darren Mann		JOB/ORDER # 7477	REFERENCE TEXT Client reference	
FIRST NAME Hiromi		LAST NAME Yoshimine			
BILLING ADDRESS COMPANY / BILLING NAME PH5 - 2088 WEST 11TH AVE VANCOUVER, V6J 2C9 BRITISH COLUMBIA, CANADA		19	PH5 - 2088 WEST 1 VANCOUVER, V6J	SERVICE ADDRESS PH5 - 2088 WEST 11TH AVE, BUZZER PH5 VANCOUVER, V6J 2C9 BRITISH COLUMBIA, CANADA	
PHONE 778.960.3375			EMAIL hiroanny@yahoo.co	.jp	

REASON FOR TODAY'S CALL: Ikea Lav sink leaking below sink.

DESCRIPTION OF WORK PERFORMED:

The lavatory drain body was not fully secured to the sink. I removed the drain body, cleaned it, and reinstalled. Tested by filling and draining the sink multiple times.

TECHNICIAN RECOMMENDATIONS:

QTY.	CODE	DESCRIPTION			PRICE
1	1/2	Labour		\$109.00	\$109.00
Gwe us Feedback WARRANTY: PA			ARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45
		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$114.45
		we did.	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE