



DATE 2017-07-12	TECHNICIAN Darren Mann	JOB/ORDER # 7496	REFERENCE TEXT Client reference
FIRST NAME Svetlana		LAST NAME Ferguson	
BILLING ADDRESS COMPANY / BILLING NAME 709 - 888 HOMER ST VANCOUVER , V6B0H7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 709 - 888 HOMER ST BUZZER: 0165 VANCOUVER , V6B0H7 BRITISH COLUMBIA, CANADA	
PHONE 604-356-5923		EMAIL svsokolo@gmail.com	

REASON FOR TODAY'S CALL:
Garburator is not working and is leaking from the bottom.

DESCRIPTION OF WORK PERFORMED:
The garburator was leaking from the bottom and was cracked where the drain connects to it. I replaced the garburator with new and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Badger5 Garburator	\$319.00	\$319.00
SUBTOTAL:				\$319.00
GST (5%):				\$15.95
TOTAL:				\$334.95

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



 CUSTOMER SIGNATURE

2017-07-12

 DATE