



HST #837181627

DATE 2017-07-14	TECHNICIAN Darren Mann		JOB/ORDER # 7511		REFERENCE TEXT Client reference
FIRST NAME Vivian		LAST NAME Zhao			
BILLING ADDRESS COMPANY / BILLING NAME 805 - 5782 BERTON AVE VANCOUVER, V6S 0C1 BRITISH COLUMBIA, CANADA		9		SERVICE ADDRESS  805 - 5782 BERTON AVE BUZZER: 1081 VANCOUVER, V6S 0C1 BRITISH COLUMBIA, CANADA	
PHONE 778.681.2633				EMAIL yuxi.zhao28@gmail.com	

REASON FOR TODAY'S CALL:

<u> Thank You!</u>

The bathtub is clogged.

## DESCRIPTION OF WORK PERFORMED:

I used the PowerSpin drain snake to clear hair from the tub drain and tested by filling the tub 8" and draining.

CHARGES. E. & O. E.

QTY.	CODE		DESCRIPTION			
1		Clean drain using Po	owerSpin /	Tub/Shower	\$149.00	\$149.00
<i>Q</i>	(1	eedlack"	VARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00
	Gwe us Feedback Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.			AC:	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$156.45
		· ·	MADE THAT	THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, ISTED, DETERIORATION, OR LEAD PIPES, EXITURES, CLEAN OUTS AND ANY OTHER DAMAGES.		

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

CUSTOMER SIGNATURE

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2017-07-14

DATE