

HST #837181627

DATE 2017-08-09	TECHNICIAN Darren Mann		JOB/O 7587	RDER #	REFERENCE TEXT Client reference
FIRST NAME Karina		LAST NAME Edora	7		
BILLING ADDRESS COMPANY / BILLING NAME #311 - 1255 SEYMOUR ST BUZ#636 VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA		19	4	#311 - 1255 SEYMOUR ST BUZ#636 VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA	
PHONE 604.418.7439				EMAIL kedora@telus.net	

## REASON FOR TODAY'S CALL:

Thank You!

There is a gurgling noise that sounds like it is coming from the bathtub drain which happens occasionally when the toilet is flushed. Darren mentioned that he may need to use the snake on the drain. Also, the bathroom sink may need the snake to it as well.

## DESCRIPTION OF WORK PERFORMED:

I used the PowerSpin drain snake to clear hair from the tub and lavatory drains. Tested and flowing freely.

QTY.	CODE	DESCRIPTION			PRICE
1		Clean drain using PowerSpin	\$149.00	\$149.00	
Gwe us Feedback  Please visit our feedback page at:		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$7.45
www.yaletownplumbing.com/feedback [1]					\$156.45
Fill in the required details from your invoice and tell us how we did.		we did.  MADE THA	AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY IT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND S LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, BUSTED, DETERIORATION OR I FAD PIPPS SEXTURES CLEAN OUTS AND ANY OTHER DAMAGES.		

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

CUSTOMER SIGNATURE

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2017-08-09

DATE