

HST #837181627

DATE 2017-08-17	TECHNICIAN Darren Mann		JOB/ORDER # 7624	REFERENCE TEXT Client reference	
FIRST NAME Jennifer		LAST NAME Perutka			
BILLING ADDRESS COMPANY / BILLING NAME 505 - 888 HOMER ST VANCOUVER, V6B 0H7 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 505 - 888 HOMER STREET BUZZER: 0025 VANCOUVER, V6B 0H7 BRITISH COLUMBIA, CANADA		
PHONE 778-995-3086			EMAIL jenn.perutka@gmail.co	EMAIL jenn.perutka@gmail.com	

REASON FOR TODAY'S CALL:

Garburator stopped working and reset button won't reset it.

DESCRIPTION OF WORK PERFORMED:

I was able to unjam the garburator by removing a small pebble that was lodged in the grinding chamber. Tested by filling the sink 6" and draining while running the

garburator. OTY. CODE DESCRIPTION UNIT PRICE PRICE							
QTY.	CODE		DESCRIPTION		PRICE		
1	/	Labour		\$109.00	\$109.00		
Q	(1	war	TY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00		
Gwe us Feedback Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45		
www.yaletownplumbing.com/feedback [1] Fill in the required details from your		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY		\$114.45		
	Thank You!		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.				

CUSTOMER SIGNATURE

DATE