

(B) @SimplyPlumbing | YaletownPlumbing

2017-08-23

HST #837181627

DATE 2017-08-23	TECHNICIAN Darren Mann		JOB/ORDER # 7645	REFERENCE TEXT Client reference	
FIRST NAME Bettina LAST NAM Sy		LAST NAME Sy	ME		
BILLING ADDRESS COMPANY / BILLING NAME 1958 - 38 SMITHE ST VANCOUVR, V6B 0P3 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 1958 - 38 SMITHE ST BUZZER: #5628 1.415.722.9622 VANCOUVR, V6B0P3 BRITISH COLUMBIA, CANADA		
PHONE 604.561.5961		EMAIL bettinamsy@gmail.co	EMAIL bettinamsy@gmail.com		

REASON FOR TODAY'S CALL:

Leak under bathroom sink(master)

DESCRIPTION OF WORK PERFORMED:

The leak was coming from the lavatory drain stopper leaver arm. The nut that secures it in place worked itself loose. I tightened this nut and tested by filling and draining the sink multiple times.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//	Labour	\$109.00	\$109.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$109.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS	ON REPAIR, VOID AFTER 30 DAYS IF S, OR PAYMENT NOT MADE, ABSOLUTELY NO	\$5.45
			TOTAL:	\$114.45
		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY MATERIALS LISTED HEREON ARE CORRECT, YALETOWN P	COMPLETED AND THAT CHARGES AND LUMBING IS NOT RESPONSIBLE FOR BROKEN, URES, CLEAN OUTS AND ANY OTHER DAMAGES TURES OR PIPING.	

CUSTOMER SIGNATURE