

(B) @SimplyPlumbing | | YaletownPlumbing

HST #837181627

DATE 2017-08-28	TECHNICIAN Darren Mann		JOB/ORDER # 7643		REFERENCE TEXT Client reference
FIRST NAME Erica		LAST NAME Timmerman			
BILLING ADDRESS COMPANY / BILLING NAME 423 - 2680 WEST 4TH AVE VANCOUVER, V6K 4S3 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 423 - 2680 WEST 4TH AVE BUZ#423 VANCOUVER, V6K 4S3 BRITISH COLUMBIA, CANADA	
PHONE 604.671.4892				EMAIL Erica.timmerman@gmail.com	

REASON FOR TODAY'S CALL: Garburator has stopped working

DESCRIPTION OF WORK PERFORMED:

The garburator grinding chamber was freely turning but the motor was seized. I replaced the garburator with a new Badger 5 and tested by filling and draining both sides of the sink multiple times while running the garburator.

QTY.	CODE		UNIT PRICE	PRICE	
1		Supply & Install 1/2	HP Badger5 Garburator	\$319.00	\$319.00
Q.,,,,		and a ale	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$319.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$334.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE