

HST #837181627

DATE 2017-08-30	TECHNICIAN Darren Mann		JOB/O 7661	RDER #	REFERENCE TEXT Client reference
FIRST NAME Dunowen Properties		LAST NAME Admin	7		
BILLING ADDRESS DUNOWEN PROPERTIES 201 - 1288 ALBERNI STREET VANCOUVER, V6E 4N5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 605 - 1211 MELVILLE ST VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.1900				EMAIL operations@dunowen.com	

REASON FOR TODAY'S CALL: kitchen faucet spray head broken

## DESCRIPTION OF WORK PERFORMED:

I replaced the broken kitchen faucet spray head and tested.

<b>QTY.</b>	CODE	DESCRIPTIO	UNIT PRICE	PRICE		
1		Discount Labour		\$99.00	\$99.00	
1	1.	Dual Spray Deck Faucet Pullout Head	\$30.00	\$30.00		
0	G	WARRANTY: PARTS - SUBJECT TO MANUFA	VARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			
Guve us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNI	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		\$6.45	
		from your	PPLIED MATERIALS.	TOTAL:	\$135.45	
		MATERIALS LISTED HEREON ARE CORRECT. Y	TISFACTORY COMPLETED AND THAT CHARGES AND ALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES XISTING FIXTURES OR PIPING. HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK			
			2017-08-30			
		CUSTOMER SIGNA	TURE DATE			